

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	L1	0	atsuta-akira.in.	USPAT	2003/04/17 16:46	
2	BRS	L2	68	atsuta-\$.in.	USPAT	2003/04/17 16:48	
3	BRS	L3	17070	(modem\$1 or transceiver\$1) same (transmission same reception\$1 or receiving same transmitting or receiver\$1 same transmitter\$1)	USPAT	2003/04/17 16:59	
4	BRS	L4	16	(modem\$1 or transceiver\$1) same (transmission same reception\$1 or receiving same transmitting or receiver\$1 same transmitter\$1) same (calling near2 terminal or answering near2 terminal or answering near2 side)	USPAT	2003/04/17 16:58	
5	BRS	L5	184	(modem\$1 or transceiver\$1) same (transmission same reception\$1 or receiving same transmitting or receiver\$1 same transmitter\$1) and (calling near2 terminal or answering near2 terminal or answering near2 side)	USPAT	2003/04/17 16:59	
6	BRS	L6	22	(detect\$4 same recommendation\$1 same answer\$3) and 3	USPAT	2003/04/17 17:01	
7	BRS	L7	2	(detect\$4 same recommendation\$1 same answer\$3) and 5	USPAT	2003/04/17 17:01	
8	BRS	L8	22	6 or 7	USPAT	2003/04/17 17:14	
9	BRS	L9	10	("T.30" same recommendation\$1 or DIS or RTDIS or identification\$1 adj1 signal\$1) and 8	USPAT	2003/04/17 17:23	
10	BRS	L10	6	("T.30" or "T. 30") and 8	USPAT	2003/04/17 17:21	

	Error Definition	Er ro rs
1		0
2		0
3		0
4		0
5		0
6		0
7		0
8		0
9		0
10		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
11	BRS	L11	118	("T.30" same recommendation\$1 or "T. 30" same recommendation\$1 or DIS or RTDIS or identification\$1 adj1 signal\$1) same 3	USPA T	2003/04/17 17:25	

	Error Definition	Er ro rs
11		0